

~~TOC~~

## PCs tested with the TimeHarp260

We have unfortunately encountered compatibility problems of the TimeHarp 260 with a few desktop PCs. The problems are mostly found with the low-end PCs of large manufacturers like DELL and are caused by a wrong implementation of the Active State Power Management (ASPM) in the BIOS of these PCs. For all non-listed motherboards/computers a general rule is that TimeHarp should not be connected directly to the processor. You should search for a PCle slots that are connected via the chipset (mostly all PCle x1 or PCle x4 Slots). The motherboard manual should contain info regarding whether a particular slot is connected directly or via chipset to the processor.

If your PC is not compatible please contact <a href="http://support.picoquant.com">http://support.picoquant.com</a>.

## working mainboards / computer

<u>-</u>	C
-	Comment
AMD 880G/SB710	
VIA K8T890/VT8237A	
AMD 770/SB600	
NVIDIA nForce4 SLI	
Intel® Z77	
Intel C602-A	only in Slot1 (lowest PClex8 Slot)
Intel Z97	
Intel Z170	
Intel Z170	
Intel H61	
Intel Z68	
Intel Z87	
Intel G33/ICH9R	
Intel P31/ICH7	
Intel P55	
Intel P55	
Intel Z68	OK after BIOS-Update to V25.8
Intel Z68	
Intel Z68	
Intel C612	works best in the 2 black PCIe x8 Slots
	AMD 770/SB600  NVIDIA nForce4 SLI Intel® Z77 Intel C602-A Intel Z97 Intel Z170 Intel Z170 Intel H61 Intel Z68 Intel Z87 Intel G33/ICH9R Intel P31/ICH7 Intel P55 Intel P55 Intel Z68 Intel Z68 Intel Z68 Intel Z68 Intel Z68

Computer	Chipset	Comment
HP ENVY 700-056	AMD A75 FCH	
Dell Precision T3400	Intel X38	Installed in SLOT 3 , PCle 8x(4,1)

© PicoQuant GmbH 1/2

not-working mainboards / computer

Computer	Chipset	Comment
DELL Vostro 630		
DELL Optiplex 9020 Model Minitower		
DELL Optiplex 7020		
DELL T7610		
HP 200-G1 (Model L5L54US#ABA)		
Lenovo ThinkServer TS140		

Copyright of this document belongs to PicoQuant GmbH. No parts of it may be reproduced, translated or transferred to third parties without written permission of PicoQuant GmbH. All information given here is reliable to our best knowledge. However, no responsibility is assumed for possible inaccuraciesor omissions. Specifi cations and external appearances are subject to change without notice.



PicoQuant GmbH Rudower Chaussee 29 (IGZ) 12489 Berlin Germany P +49-(0)30-1208820-89 F +49-(0)30-1208820-90 info@picoquant.com www.picoquant.com

© PicoQuant GmbH 2/2